



Product Technical Data Sheet

Form No.: FTP-007 Rev.: H

Product Name: SteriTec Cross-Checks P Indicator

Product Type: Process Indicator

Reorder Number: CI 115

Description: The SteriTec Cross-Checks P process indicator was designed for use in a Sterrad® sterilizer. The Cross-Checks P will exhibit a color change when exposed to hydrogen peroxide during the diffusion stage of the sterilization cycle. When utilized properly the Cross-Checks P will give visual confirmation that the item was exposed to hydrogen peroxide.

Performance Characteristics:

When exposed during a Sterrad® sterilization process, the check marks will change color.

Color Change: Blue to Pink

Complete Color Change Time: 30 minutes +/- 5 min

Indicator Stability: Before and After Sterilization = Excellent

Physical Characteristics:

Dimensions: 0.5625" W X 3.8" L

Indicator Substrate Material: Polystyrene

Quantity / Bag: 250

Bags / Case: 24

Selling Unit: Case

Environmental Limitations:

Storage: 50° - 100°F (10° - 38°C) at 10 - 90% humidity, when stored in re-sealable moisture barrier bag provided.

Shelf Life: The expiry date is printed on the product packaging.

FDA 510(k) Release to Market Date: March 25, 1998, K972300

Standards Classifications: N/A